



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program April 20, 2011:

Reviewed: 

| | |
|---------------------------------------|---------------------------------|
| Mine Name: Lucero Red | Permit Number: S/055/0023 |
| Operator Name: Quality Building Stone | Inspection Date: April 20, 2011 |
| Inspector(s): Wayne Western | Time: 2:40 -3:40 |
| Other Participants: | Mine Status: Active |

| Elements of Inspection | Evaluated | Comment | Enforcement |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. Deleterious Material | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Concurrent Reclamation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Water Impoundments | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Soils | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Re-vegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. Air Quality | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond is \$22,000.00 and the renewal date is January 19, 2009. The GPS done on the site in 2008 shows a disturbed area of 12 acres.

Large rock placed at main pit to prevent access.

Site was inactive during inspection.

Some trash on site that should be cleaned up.

Conclusions and Recommendations:

The Division should have the Operator reclaim down to 10 acres.

Inspector's Signature _____

WHW

cc: (OPERATOR)

O:\M055-Wayne\S0550023-LuceroRed\inspections\Insp-04202011.doc




Working pit



Pit roads



Pit with water



Looking south